

Index File No. R-17

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 73 R. 36E

R.D. LA CERRILLO County UNION

Merid. will

N.F. W-W State OR

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

PILE OF ROCKS

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

SEC. 23 - 14" P.R. - LIVE - VISIBLE SCAR
SEC. 26 - 38" P.R. - LIVE - SCRIBE VISIBLE
SEC. 27 - BURNED STUMP - NO SCRIBE EVIDENCE
SEC. 22 - 26" P.R. - LIVE - VISIBLE SCAR.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER FALLS AT S.E. CORNER
OF SMALL CLEARING. SMALL DRAW
100' TO THE SOUTH.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

Signature JAMES LUSHER

Title _____ Division _____ Headquarters 6/14/86 Date _____ FS-7100-52 (3/68)

UNION COUNTY SURVEYOR	
Date Received	_____
Date Filed	<u>12-21-87</u>
By	<u>S. LANGLITZ, DEPUTY</u>
File No.	<u>310-87R</u>

R-17