
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: None

No record of subsequent monumentation found in Union County survey records.

Description of corner evidence found: NONE

See Union County Survey 022-1996



Description of monument and accessories I established

to perpetuate the original location of this corner:
At position determined by survey I set a 25" x 30" aluminum pipe with 25" cap marked as shown below, 20" in the ground, with a mound of stone 3 ft. in diameter at the base, from which:

A 15" Ponderosa Pine bears S29°E, 242.95 feet, marked E 1/16 S5 BT.

A 18" Ponderosa Pine bears S65°W, 106.62 feet, marked X BT.

Placed steel fence post approximately 5 feet north with land survey monument sign attached.

I hereby certify that the corner was monumented on May 30, 1996. Witness: Mark Durbin

> REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON

JEFFERY P. PETERSEN 2625

Renewal Date: December, 31 1996



UNION COUNTY SURVEYOR

Date Received 5-31-96

Date Filed 5-3/-96

Filed By R. ROBINSON, DEFUTY

File Number 055-1996 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer to BT blaze.

A-08