


UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner nor previously established

T 4S R 37 E B-05



DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey Number 009-2009

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8"x30" iron pin 2 1/2" aluminum cap marked as shown, 28" in the ground, from which:


NEW BEARING TREES

A 16" diameter Douglas Fir Pine bears North 2° West, a distance of 90.20 feet, marked N 1/16 S5 BT

A 14" diameter Ponderosa Pine bears North 52° West, a distance of 68.37 feet, marked N 1/16 S6 BT

Set steel fence post approximately 2 feet North of monument.

I hereby certify that the corner was monumented on May 4, 2009



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2010

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer marked OPLS 2219 to BT blaze.

UNION COUNTY SURVEYOR

Date Received 5/6/09

Date Filed 5/6/09

Filed By [Signature]

File Number 006-200912

B-05