RTIFIED RECORD OF LAND CORNER MONUMEN. ATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 013-2009

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with 2 ½" aluminum cap marked as shown, 27" in the ground, from which:

- A 17 inch Douglas Fir bears South 19° West, a distance of 10.45 feet, marked W 1/16 S10 BT.
- A 21 inch Douglas Fir bears North 32° West, a distance of 30.72 feet, marked W 1/16 S3 BT.

Set a steel fencepost 1 foot West of corner.

I hereby certify that the corner was monumented on June 16, 2009 Witness: Jeff Hsu, Gregory T. Blackman, Jr.

PROFESSIONAL LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON 2219

Renewal Date: December 31, 2010

......

S 3 W 1/16 S 10 2009 OPLS 2219

T4S R37E E-14

10

S

UNION COUNTY SURVEYOR

Date Received 6/25/89

Date Filed 6/29/0

1027-7009 R

I used a steel tape and magnetic compass in the establishment of the accessories. Magnetic declination is 18° East. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance is to a 60d spike driven into the root crown at the right side of the bearing trees.