RTIFIED RECORD OF LAND CORNER MONUMEN ... ATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 013-2009
DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with aluminum cap marked as shown, 29" in the ground, from which:

- A 10 inch Ponderosa Pine bears South 13° West, a distance of 11.61 feet, marked S 1/16 S9 BT.
- A 13 inch Douglas Fir bears North 61° West, a distance of 36.25 feet, marked S 1/16 S9 BT.


I set a steel fencepost 1 foot East of the corner.

I hereby certify that the corner was monumented on June 11, 2009 Witness: Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR
OREGON
July 17, 1986

RICK G. ROBINSON 2219

Renewal Date: December 31, 2010



T4S R37E H-13

10

S

UNION COUNTY SURVEYOR

Date Received 6/25/69

Date Filed 6/29/09

Filed By Lyn 7. Blow

____ 020 - 70091

I used a steel tape and magnetic compass in the establishment of the accessories. Magnetic declination is 18° East. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance is to a 60d spike driven into the root crown at the right side of the bearing trees.