RTIFIED RECORD OF LAND CORNER MONUMEN. .TION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 013-2009
DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with aluminum cap marked as shown, 12" in the ground, with mound of stone 3 ft. wide, from which:

A 16 inch Ponderosa Pine bears South 56° West, a distance of 63.27 feet, marked SW 1/16 S10 BT.

A 5/8" x 12" iron pin, driven to bedrock bears North 42° West, a distance of 32.84 feet, with 1 $\frac{1}{2}$ " Aluminum Cap marked NW RP.

I set a steel fencepost 2 feet North of the corner.

I hereby certify that the corner was monumented on June 11, 2009 Witness: Jeff ${\tt Hsu}$


REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

July 17, 1986

RICK G. ROBINSON 2219

Renewal Date: December 31, 2010



T4S R37E H-14

10

S

UNION COUNTY
SURVEYOR

Date Received 6/25/09

Data Filed 6/29/6

Filed By Lyn T. Blar C

File Number 024-7009 K

I used a steel tape and magnetic compass in the establishment of the accessories. Magnetic declination is 18° East. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance is to a 60d spike driven into the root crown at the right side of the bearing tree and to the center of the aluminum cap.