## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


## HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner originally established by Hermon D. Gradon under GLO contract number 452, dated June 6, 1882 Surveyor General record states:

Set Basalt stone 15"x8"x6" marked 1/4 on North face, set 10 inches in the ground, from which;

A Pine 14" dia. bears N20°W, 28 lks., marked 1/4 S BT.

A Pine 20" dia. bears S 50°E 20 lks., marked 1/4 S BT.



## DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey No. 008-2009

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position established by Survey 008-2009, I set a 2 ½" Aluminum pipe with aluminum cap marked as shown, 18 inches in the ground, with a small 2' mound of stone, from which:

A 10" Western Larch that bears North 35° West, 4.85 feet, marked 1/4 S8 BT

A 6" Ponderosa Pine that bears South 56°East, 68.58 feet, marked "X" BT

A 14" Western Larch that bears South 89°West, 45.43 feet, marked 1/4 S17 BT


A 14" Western Larch that bears North 75°West, 47.32 feet, marked 1/4 S8 BT

Set Steel fence post 2 feet West of corner.

I hereby certify that the above corner point was monumented as hereon described on May 8, 2009. Witness: Gregory T. Blackman, Jr.

**REGISTERED PROFESSIONAL** LAND SURVEYOR ORÉGON RICK G. ROBINSON 2219

Renewal Date: December 31, 2010



**UNION COUNTY SURVEYOR** -7009 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I use 18° East declination. The distances are to a 60d spike driven into the right side of the root crown of the bearing trees. Attached brass washer marked OPLS 2219 to BT Blaze.