


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.

K-19



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR
Dist. Received <u>1-5-89</u>
Filed <u>1-6-89</u>
By <u>G. LANGRITZ, DEPUTY</u>
File No. <u>12-89R</u>

Description of monument and accessories | established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 15" in ground, to rock surrounded with mound of earth and stone & 6' steel fence post West of corner and attached sign 54-9 and 54-2. Cap marked as shown in corner diagram.

New bearing trees established:

A 10" western larch brs N37½°W, 71.4' scribed C-N1/16S14 BT.

A 7" western larch brs S44½°W, 57.3' scribed C-N1/16S14 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 29, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of.....County Surveyor..... County of.....Union
State of.....Oregon....., I hereby certify that the within instrument was filed in this office

for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)