


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L-15

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR
Date Received <u>1-5-89</u>
Date <u>1-6-89</u>
By <u>G. LANGLITZ DEPUTY</u>
File No. <u>14-89 R</u>

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 24" in ground, surrounded with mound of earth and stone & 6' steel fence post North of corner with sign 54-9 attached. Cap marked as shown in corner diagram.

New bearing trees established:

A 7" western larch brs S17°W, 54.9' scribed C1/4S15 BT.

A 15" western larch brs N50½°E, 108.8' scribed C1/4S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 23, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>William R. Wells</i>
OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)