


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

UNION COUNTY SURVEYOR

Date Received 1-5-89

Filed 1-6-89

By G. LANGRISH, DEPUTY

File No. 15-89 R

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 24" in ground surrounded with mound of earth only, and a 6' steel fence post E & S of corner and attached sign 54-9 to one & 54-2 to both. Cap marked as shown in corner diagram.

New bearing trees established:

- A 12" lodgepole pine brs S42½°W, 47.6' scribed C-E1/16S15 BT.
- A 6" western larch brs S27°E, 66.9' scribed C-E1/16S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 23, 1988.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of.....County Surveyor..... County of.....Union.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....

..... by
 (COUNTY OFFICIAL) (DEPUTY)