RTIFIED RECORD OF LAND CORNER MONUMEN. ATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 015-2009

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with 2 ½" aluminum cap marked as shown, 27" in the ground, from which:

- A 9 inch Ponderosa Pine bears South 64° East, a distance of 26.33 feet, marked S 1/16 S17 BT.
- A 7 inch Douglas Fir bears North 75° West, a distance of 40.25 feet, marked S 1/16 S18 BT.

I set a steel fencepost 1 feet South of the corner.

I hereby certify that the corner was monumented on July 10, 2009 Witness: Jeff Hsu, Gregory T Blackman, Jr.


REGISTERED PROFESSIONAL LAND SURVEYOR

OREGÓN

RICK G. ROBINSON

2219

Renewal Date: December 31, 2010



T4S R37E M-05

17

S

UNION COUNTY SURVEYOR

Date Received 7/13/09

- Lague 20, 9—

File Number $\frac{\checkmark 631 - 6009}{}$

I used a steel tape and magnetic compass in the establishment of the bearing tree accessories. Magnetic declination is 18° East. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance is to a 60d spike driven into the root crown at the right side of the bearing trees.