

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Union County Survey Number 015-2009
DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin, with 2 ½" aluminum cap marked as shown, 26" in the ground, from which:

- A 16 inch Douglas Fir bears South 85° East, a distance of 31.20 feet, marked SW 1/16 S17 BT.
- A 14 inch Douglas Fir bears North 43° West, a distance of 76.50 feet, marked SW 1/16 S17 BT.

I set a steel fencepost 1 feet West of the corner.

I hereby certify that the corner was monumented on July 10, 2009 Witness: Jeff Hsu, Gregory T Blackman, Jr.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

RICK G. ROBINSON

2219

Renewal Date: December 31, 2010

SW 1/16

S 17

2009

OPLS 2219

T4S R37E M-06

17

S

UNION COUNTY SURVEYOR

Date Received 1/13/09

Date Filed 8 15 109

File Number 03L-LLOG 16

I used a steel tape and magnetic compass in the establishment of the bearing tree accessories. Magnetic declination is 18° East. I attached a brass washer marked OPLS 2219 to the BT blaze. The distance is to a 60d spike driven into the root crown at the right side of the bearing trees.

M-06