


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.

M-14



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR	
Date Received	<u>1-5-89</u>
Date Filed	<u>1-6-89</u>
By	<u>G. LANGLITZ DEPUTY</u>
File No.	<u>19-89 R</u>

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 22" in ground surrounded with mound of earth and stone & 6' steel fence post S & E of corner and attached sign 54-9 to one & 54-2 to both. Cap marked as shown in corner diagram.

New bearing trees established:

- A 14" white fir brs S52°E, 22.1' scribed SW1/16S15 BT.
- A 12" white fir brs N8½°W, 27.0' scribed SW1/16S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 27, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR
<i>William R. Wells</i>
OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

M-14