


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

M-15

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR
Date Received <u>1-5-89</u>
Date Filed <u>1-6-89</u>
By <u>G. LANGRISH DEPUTY</u>
File No. <u>20-89 R</u>

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 20" in ground surrounded with mound of earth and stone & 6' steel fence post E & W of corner and attached sign 54-9 to one & 54-2 to both. Cap marked as shown in corner diagram.

New bearing trees established:

- A 12" white fir brs N75°E, 11.2' scribed C-S1/16S15 BT.
- A 14" white fir brs S29½°W, 73.9' scribed C-S1/16S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 27, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County Surveyor..... County of..... Union
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)

M-15