


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established as part of this survey.

M-16



Description of corner evidence found:

None.

UNION COUNTY SURVEYOR	
Date Received	<u>1-5-89</u>
Date Filed	<u>1-6-89</u>
By	<u>G. LANGRISH DEPUTY</u>
File No.	<u>21-89 R</u>

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 24" in ground surrounded with mound of earth and stone & 6' steel fence post North of corner and attached sign 54-9 and 54-2. Cap marked as shown in corner diagram.

New bearing trees established:

A 16" douglas fir brs S1½°W, 52.3' scribed SE1/16S15 BT.

A 14" western larch brs N24½°W, 36.8' scribed SE1/16S15 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 27, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County Surveyor..... County of..... Union.....

State of..... Oregon....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by.....
(COUNTY OFFICIAL) (DEPUTY)

M-16