## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 48, R 37E., W.M.

Corner Code No. N-7
Note: Monument marked as shown below

## History of original corner establishment:

This corner was originally established by Herman D. Gradon, U.S. Deputy Surveyor, under Contract No. 452, dated June 16, 1882. The original notes state that at the corner a 18 by 6 by 5 inch basalt stone, marked 1/4 on north face was set 12 inches in the ground from which:

A pine 20 ins diem. bears N20°M 22 lks dist., marked 1/4 S. BT. A pine 8 ins diam. bears S10°E 24 lks dist., marked 1/4 S. BT.

DIAGRAM
T4S R37E
$1/4 = \frac{\$17}{\$20}$
1988
PLS 1106

Corner No. Compass Declination: 19.0 =

#### Description of corner evidence found:

None. This corner was searched for a total of 8.0 hours with a 2 person crew including a PLS. The corner was searched on 3 separate occasions. One 20" down ponderosa pine located about 150 feet east of corner point was opened with a chain saw, and axe marks were exposed, but the axe marks and chopped face are not similar to other original axe marks and blaze faces found on this survey.

No evidence of scribes exist on the chopped face of the 20" ponderosa pine.

There is evidence of logging and camping in the area. Stones have been gathered for several camp fire rings in the area.

# Description of monument and accessories I established to perpetuate the original location of this corner:

This corner was reestablished by single proportion measurement between the recovered NW and NE corners of Section 20. At the reestablished corner point, I set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap 14" in the ground to rock and surrounded with a mound of earth and stone. Marked 2 new

A 10" ponderosa pine bears N56 1/2°W 14.2' scribed 1/4 S 17 BT. A 19" ponderosa pine bears S38 1/2°E 76.0' scribed 1/4 S 20 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to the face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post west of corner and attached sign 54-2 and 54-9.

## UNION COUNTY SURVEYOR

Date Received 1-5-89

Date Filed 1-6-89

By Co. LANGLITZD

File No. 23-89 R

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
WILLIAM R. WELLS

1106

Office of	County of
for record on the day of	hat the within instrument was filed in this offica
(COUNTY OFFICIAL)	(DEPLITY)