CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Original Survey by General Land Offices (Contract Survey 1882)

The original notes read; Set a post from which: A fir 10° in diam bears N15°E 10 lks dist marked $\frac{1}{4}$ SBT; A fir 8° in diam bears S20°W 9 lks dist marked $\frac{1}{4}$ SBT:

M-11

DIAGRAM

T4S R37EWM

S16

S21

Description of corner evidence founds

Found- A fir 10" in diam bears N15°E 10 lks dist with blaze scar. Found Fir 13" in diam bears S20°W 9 lks dist with scribe visible.

REGISTERED
OREGON
LAND SURVEYOR

MAY 4, 1956
JAMES G. VOELZ
381

Description of monument and occassories t established to perpetuate the original location of this corner

At the position of the corner I set A galvanized pipe 30" long with a bronze cap on top and 8" plate welded to bottom. Pipe set to a depth of 21" and backfilled with stone and soil

I stamped the disk

From the position of the corner the original bearing trees are; A fir 10" in diam bears N15°E 10 lks dist. A fir 13" in diam bears S20°W 9 lks dist.; I set a steel fence post with USFS sign 54-4 attached; I placed a National Forest Boundary sign on the post indicating National Forest Land to South. Bearing tree signs were placed on bearing trees shoulder high facing the corner.

\$16 \$21 ORE LIC 381 1969

Office of	Union UNION COUNTY	
Office of	19, o'clock	
County Surveyor (COUNTY OFFICIAL)	(DEPUTY) Date Received	-
	Date Filed	-
	File No. 504-84 R	-