
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not set during original GLO survey.

Description of corner evidence found: None

Description of monument and accessories I established to perpetuate the original location of this corner: I set a 5/8" x 30" rebar with 2 ½" aluminum cap 29" in the ground, marked as shown see (Union

County Survey number 020-2010), from which:



NEW BEARING OBJECTS:

A 15 "White Fir bears S 49°E, a distance of 36.77 feet, marked E 1/16 S21 BT.

A 7 "Lodge Pole Pine bears N 16°W, a distance of 12.75 feet, marked E 1/16 S16 BT.

Fence Post with U.S.F.S. Boundary sign is 1 foot Northeasterly of monument, and Fence Line running East and West is located approximately 2.50 feet North of monument.

I hereby certify that the corner was monumented on August 11, 2010 Witness: Greg Blackman Jr. & Jeff Hsu

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
July 17, 1986
RICK G. ROBINSON
2219

Renewal Date: December 31, 2010

UNION COUNTY
SURVEYOR

Date Received 8/17/2010

Date Filed B/17/2010

Filed By Ly 7. Blow

File Number 030-2010 R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven into the root crown at the right side of the bearing trees. Attached brass washer marked OPLS 2219 to BT blaze.