


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

N-14

History of original corner establishment:

None. Corner established as part of this survey.



Description of corner evidence found:

None.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>1-5-89</u>
Date Filed	<u>1-6-89</u>
By	<u>G. LANGRIZ, Deputy</u>
File No.	<u>26-89 R</u>

Description of monument and accessories established to perpetuate the original location of this corner:

At position established by survey...

Set a 2½" aluminum cap on 2½ x 30" aluminum pipe 15" in ground, to rock, surrounded with mound of earth and stone & 6' steel fence post West of corner with sign 54-9 and 54-2. Monument is intentionally leaned North to avoid root. Cap marked as shown in corner diagram.

New bearing trees established:

A 20" ponderosa pine brs N21½°E, 42.2' scribed W1/16S15 BT.

A 10" ponderosa pine brs S30½°E, 66.5' scribed W1/16S22 BT.

New BTs have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9, painted face of blaze & a 6" red band around each BT.

Compass declination 19° East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on October 25, 1988.

REGISTERED PROFESSIONAL LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Office of.....County Surveyor..... County of.....Union  
State of.....Oregon.....

I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)