

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 4 S R 37 E N-22

S	24

DESCRIPTION OF CORNER EVIDENCE FOUND:

None Found

SEE SURVEY NUMBER 032-2017

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin 28" in the ground with 2 1/2" aluminum cap marked as shown below.

From which:

A 11" Ponderosa Pine bears N20°E, a distance of 73.60 ft dist, marked W1/16 S13 BT.


A 10" Douglas fir bears S78°E, a distance of 57.40 ft dist, marked W1/16 S24 BT.

Set steel fencepost approx. 1 ft. North of monument

I hereby certify that the corner was monumented July 18, 2017.


Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019



**UNION COUNTY
SURVEYOR**

Date Received 7/26/17

Date Filed 7/26/17

Filed By [Signature]

File Number 024-2017R

I used a steel tape and magnetic compass in the establishment of the bearing trees. Magnetic declination used was 13° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze of the tree. Distance is to a spike set in the root crown of the side of the tree.