


Index File No. R-9 CORNER RECORD (SEARCH) Tract or Survey No. _____ Cor. No. _____
 T 4 S R. 37 E R.D. La Grande County Union
 Merid. Well N.F. Whitman State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Mound of dirt in center of B.T.'s could be approx corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

21" D.F. that is alive. Visible scar on a 112° azimuth.

21" W.L. that is alive. Visible scar on a 261° azimuth.

12" W.L. that is alive, visible scar on a 260° azimuth. No signs of human disturbance

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature K. Blanchard Title Forestry Aid Division _____ Headquarters _____ Date 7-9-68 7100-52 REV. 65 5

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 326-87R

R-9