History of original corner establishment: Corner not established in original survey.

None

	5-21	
DIAGRAM		
T4S R37E N1/16		
\$ 26	S 25	

No record of subsequent remonumentation found in County records. Description of corner evidence found:

NONE


See map of survey dated June 1980 Description of monument and accessories I established to perpetuate the original location of this corner:

> At a proportionate distance, I set a $2\frac{1}{2}$ inch x 30 inch iron pipe with brass cap marked as shown, 27 inches in the ground, from which;

A 10 in. dia. fir bears S8E, 58.4 feet marked N1/16 S25 BT

A 16 in. dia. fir bears S68W, 48.7 feet marked N1/16 S26 BT

REGISTERED PROMESSIONAL LAND BURYEYOR
Dund Suffer
OREGON DUANE L GRIPPITH GA 4



Brass washer nailed to B.T.blaze Used steel tape and magnetic compass with 18 East declination.
Measured to center of all

Office of	County of	· · · · · ·
the control of the co	at the within instrument was filed :-	AL 1 441
for record on the day of by	, 19	UNION COUNTY
(COUNTY OFFICIAL)	(DEPUTY)	- SOKAELOK
R6-7100-57 (9/71)		Data Received

Form

Date Filed