


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4S, R 37E. , W.M.

Corner Code No. S-22
Note: Monument marked as shown below

History of original corner establishment:

None. The corner was established as part of this survey.



Corner No.
Compass Declination: 19.0° E

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the the corner position determined by survey, I set a 2 1/2" by 30" aluminum pipe with 2 1/2" aluminum cap 24" in the ground and surrounded with a mound of earth and stone from which:

- A 21" douglas fir bears S86° E 16.6' scribed NW 1/16 S25 BT.
- A 19" douglas fir bears S2 1/2° W 42.4' scribed NW 1/16 S25 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to the face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence posts North and West of corner and attached sign 54-9 to one post and sign 54-2 to both posts.

UNION COUNTY SURVEYOR
Date Received <u>1-5-89</u>
Date Filed <u>1-6-89</u>
By <u>G. LANGLITZ, DEPUTY</u>
File No. <u>32-88⁸⁹ R</u>

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....
 by
 (COUNTY OFFICIAL) (DEPUTY)