## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

T 4S, R 37E. . W.M.

History of original corner establishment:

None. The corner was established as part of this survey.

Corner Code No. T-23 Note: Monument marked as shown below

## DIAGRAM

T4S R37E C 1/4 . S25 1988 PLS 1106

Compass Declination: 19.0° €

Description of corner evidence found:

None.

## UNION COUNTY SURVEYOR

Dato Received 1-5-89

Date Filed 1-6-89

By G. LANGLITZ DEPUT

File No. 33-89 R

Description of monument and accessories I established to perpetuate the original location of this corner:

The corner point falls 5 feet South of the centerline of Road 4305, in a rock fill. Without a backhoe, it would take a considerable amount of time to bury a standard monument with the top 6" below the road surface. So, at the corner point, I set a 18" by 5/8" iron rod, with 1 1/2" aluminum cap marked as shown in diagram. The top of the aluminum cap is 6" below the road surface. I also set a 2 1/2" by 30" aluminum pipe, with 2 1/2" aluminum cap, as a witness corner monument, S 0°41' 49"W a distance of 20.00 feet from the corner point. mound of earth and stone. Two bearing trees were marked to reference the witness corner monument:

A 10" lodgepole pine bears S61  $1/2^{\circ}$ E 53.6' scribed "X" at breast height and "BT" at base. A 17" Englemann spruce bears S0  $1/2^{\circ}$ W 61.1' scribed "X" at breast height and "BT" at base. Bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post 3.0 feet South of witness corner monument and attached sign 54-9.

Witness corner cap is marked: W C & t
T4S R37E
C 1/4 . S25

PLS 1106

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 19/7
WILLIAM R. WELLS
1106

Office of	. County of
for record on the day of	hat the within instrument was filed in this office 19
(COUNTY OFFICIAL)	(DEPLITY)

Form R6-7100-57 (9/71)

GPO---798-276