

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:


Corner established in 1882 by Herman D. Gradin under General Land Office Contract No. 452.

Surveyor General Record states:

Set post for corner from which;

A fir 20 in. dia. bears S55W, 16 links

The old 1/4 Section corner bears South, 1.54 chains



No record of subsequent remonumentation found in County records.
Description of corner evidence found:

ORIGINAL BT

A fir 24 in. dia. bears S39W, 8.9 feet, live, scribes visible

See map of survey dated June 1980.

Description of monument and accessories established to perpetuate the original location of this corner:


At record distance from BT and on the range line, I set a 2 1/2" x 30" iron pipe with brass cap marked as shown, 25" in ground, from which:

NEW BT:

A 9" fir bears N26W, 8.6 feet marked 1/4 S25 BT

The West 1/4 corner of Section 30 bears South 102.95 feet

Raised mound of stone



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Duane L. Griffith

OREGON
JULY 2, 1968
DUANE L. GRIFFITH

Brass washer nailed to B.T.blaze.
Used steel tape and magnetic compass with 18° East declination.
Measured to center of all B.T.s

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR

Received _____

Date Filed _____

By _____

File No. 512-84R