
HISTORY OF ORIGINAL CORNER ESTABLISHMENT: Corner not previously set.



No record of subsequent monumentation found in Union County Survey Records
DESCRIPTION OF CORNER EVIDENCE FOUND:
None

See Survey No. 026-2002

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the proportioned position, I set a 5/8"x 30" iron pin with a  $2\frac{1}{2}$ " aluminum cap marked as shown, 26 inches in the ground, from which;

NEW BEARING TREES:

A 16 inch Tamarack bears South 14° East, a distance of 80.80 feet, marked E1/16 S5 BT.

A 14 inch Douglas Fir bears North 34° West, a distance of 75.95 feet, marked E 1/16 S 32 BT.

I hereby certify that the corner was monumented on July 12,2002 Witnesses:
Norbert Volny and Gregory T. Blackman Jr.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 13, 1973

GREGORY T. BLACKMAN 991

Renewal Date: December 31, 2003

A A A A A A A A A A A A A A A A A A A	GRIFFITH & T3S R38E	Ol PC+ NPZ
E 1/16	S 32	Z
	T4S	
	2002	
	OPLS 991	

UNION COUNTY
SURVEYOR

Date Received 7/19/62

Date Filed 7/19/62

Filed By Rikobinson, Denvi

File Number 014 - 2002 C

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 18° East declination, the distances are to a 60d spike driven in the root drown of the BT. A brass washer marked OPLS 991 is attached to the BT blaze.