


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 4 S R 38 E B-11



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 016-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin with a 2 1/2" aluminum cap marked as shown below, 26" in the ground from which:

NEW BEARING OBJECTS:

A 10" Douglas Fir bears South 6° West, a distance of 20.85 feet, marked CN 1/16 S4 BT.
A 6" White Fir bears North 49° West, a distance of 21.20 feet, marked CN 1/16 S4 BT.

Monument falls in the corner of a rock jack for East and West Bearing fences.

I hereby certify that the corner was monumented on May 4, 2018.

Witness: Kyle Tucker


REGISTERED
PROFESSIONAL
LAND SURVEYOR

Jeffrey S. Hsu
OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

UNION COUNTY
SURVEYOR

Date Received 5/29/18
Date Filed 5/29/18
Filed By [Signature]
File Number 017-2018R



I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.