

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHED:**


Corner not previously established

T 4 S R 38 E B-12

**DESCRIPTION OF CORNER EVIDENCE FOUND:**

None

See Survey Number 016-2018



**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by survey, I set a 5/8" x 30" iron pin with a 2 1/2" aluminum cap marked as shown below, 28" in the ground from which:

**NEW BEARING OBJECTS:**

A 19" Douglas Fir bears South 67° East, a distance of 11.60 feet, marked NE 1/16 S4 BT.  
An 11" Ponderosa Pine bears North 23° West, a distance of 54.45 feet, marked NE 1/16 S4 BT.

Set a steel fence post approximately 1 foot South of monument.

Monument falls in East West fence line.

I hereby certify that the corner was monumented on May 4, 2018.

Witness: Kyle Tucker

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2019

UNION COUNTY  
SURVEYOR

Date Received 5/29/18

Date Filed 5/29/18

Filed By MLG

File Number 018-2018R

BAGETT - GRIFFITH & BLACKMAN

T4S R38E

NE 1/16 S4

2018  
OPLS 83571

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.