


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 4 S R 38 E C-12



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 016-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin with a 2 1/2" aluminum cap marked as shown below, 29" in the ground from which:

NEW BEARING OBJECTS:

A 16" Douglas Fir bears South 70° West, a distance of 33.13 feet, marked CE 1/16 S4 BT.
An 11" White Fir bears North 11° West, a distance of 5.85 feet, marked CE 1/16 S4 BT.

Set a steel fence post approximately 1 foot South of monument.

I hereby certify that the corner was monumented on May 4, 2018.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

**UNION COUNTY
SURVEYOR**

Date Received 5/29/18

Date Filed 5/29/18

Filed By MGH

File Number 019-2018R

BAGETT - GRIFFITH & BLACKMAN

T4S R38E
E 1/16
C ——— C
S4
2018
OPLS 83571

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.