


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 4 S R 38 E C-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 016-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 2 1/2" x 30" aluminum pipe with a 3" aluminum cap marked as shown below, 28" in the ground in 2' diam. mound of stone.
From which:

NEW BEARING OBJECTS:

- A 15" x 5/8" iron pin bears North 48°55' East, a distance of 10.08 feet marked NE RP.
- A 15" x 5/8" iron pin bears South 49°44' East, a distance of 10.15 feet marked SE RP.
- A 15" x 5/8" iron pin bears South 37°53' West, a distance of 10.18 feet marked SW RP.
- A 15" x 5/8" iron pin bears North 42°12' West, a distance of 10.10 feet marked NW RP.

I set a steel fencepost approximately 1 foot North of corner monument.

I hereby certify that the corner was monumented on May 8, 2018.

North/South bearing fence line bears West approx. 70 ft.

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]

OREGON
June 2, 2010
JEFFREY S. HSU
83571


UNION COUNTY
SURVEYOR

Date Received 5/29/18

Date Filed 5/29/18

Filed By *[Signature]*

File Number 020-2018R



I used a Leica GS 15 GPS unit in the establishment of the new accessories. Basis of Bearing is as per map of survey number 016-2018. Distances and bearings are to the center of the 1 1/2" aluminum caps.