

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:


Corner not previously established

T 4 S R 38 E D-13

DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 016-2018



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin, 28" in the ground with a 2 1/2" aluminum cap marked as shown in 2' mound of stone from which:

NEW BEARING OBJECTS:

A 12" White Fir bears South 68° East, a distance of 21.55 feet, marked S 1/16 S3 BT.
A 7" White Fir bears South, a distance of 7.40 feet, marked S 1/16 S4 BT.

Set a steel fence post approximately 1 foot North of monument.

Monument falls in cut bank of old logging road. Remnants of old East/West barb wire fence bears approx. 60' North on South side of drainage bottom.

I hereby certify that the corner was monumented on May 15, 2018.

Witness: Kyle Tucker, Matt Griffith

REGISTERED PROFESSIONAL LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

BAGGETT - GRIFFITH & BLACKMAN

T4S R38E
S 1/16
S4 | S3
2018
OPLS 83571

UNION COUNTY SURVEYOR

Date Received 5/29/18
Date Filed 5/29/18
Filed By M. Griffith
File Number 022-2018R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.