


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established

T 4 S R 38 E D-15



DESCRIPTION OF CORNER EVIDENCE FOUND:

None

See Survey Number 016-2018

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8" x 30" iron pin, 28" in the ground with a 2 1/2" aluminum cap marked as shown below from which:

NEW BEARING OBJECTS:

A 7" Douglas Fir bears South 63° West, a distance of 3.85 feet, marked CS 1/16 S3 BT.
A 9" Ponderosa Pine bears South 76° East, a distance of 20.75 feet, marked CS 1/16 S3 BT.

Set a steel fence post approximately 1 foot North of monument.

Corner of North/South/East bearing fence lines bears North East approx. 60 ft.

I hereby certify that the corner was monumented on May 15, 2018.

Witness: Kyle Tucker, Matt Griffith

REGISTERED PROFESSIONAL LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2019

UNION COUNTY SURVEYOR

Date Received 5/29/18

Date Filed 5/29/18

Filed By Ad C. White

File Number 023-2018R

I used a steel tape and magnetic compass in the establishment of the new accessories. I used 13° East declination, the distances are to a 60d spike driven into the right side of the root crown of the bearing trees. A brass washer marked OPLS 83571 is attached to the BT blaze of the new bearing trees.