## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## History of original corner establishment:

The original survey was performed by T. Lavenpor under GLO contract No. 102 dated July 20, 1863. GLO record states:

T4S
R 37 E|R 38 E
S 12 |S 6 | |S 7 |
PLS 1206 | 1988

F-1

Set post, from which:

A pine 48" dia. bears S 55 E, 89 1ks.

A pine 16" dia. bears A 50 k, 107 lks.

## Description of corner evidence found:

Found a rotted stump, 10" high, dia. indeterminant, bears N 50 W 70.6 ft. unmarked.

A 36" dia. rotted, burned and sawed stump 30" high bears S 35 E 58.7 ft. unmarked.

| UNION COUNTY<br>SURVEYOR |  |  |
|--------------------------|--|--|
| Data Received 5-1-89     |  |  |
| Date Filed 5-15-89       |  |  |
| By G. LANGLITZ DOPLTY    |  |  |
| File No. 107-89 R        |  |  |

## Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point as reestablished from the original found bearing trees, set  $2\frac{1}{2}$ " brass cap on  $1\frac{1}{2}$ " dia. galv. iron pipe, 30" long, 20" into the ground.

From the corner point:

A 17" dia. Ponderosa Pine bears N 84 E, 76.9 ft. dist. marked T4S R38E S6 BT

 $\Lambda$  15" dia. Ponderosa Pine bears S 51 E, 45.4 ft. dist. marked T4S R38E S7 BT

Set a steel fence post alongside the monument, painted the blazes on the bearing trees red, and attached a brass I. D. washer between the B and T scribes.

I certify the above monument and references were properly established under my supervision July 27, 1988 and witnessed by Tom Fisk, Larry McBroom and Andy Marlette.

| for record on the      | , I hereby certify that th day ofby |          |
|------------------------|-------------------------------------|----------|
| COUNT                  | PROFESSIONAL                        | (DEPUTY) |
| Form R6-7100-57 (9/71) | LAND SURVEYOR                       |          |

(0,11)

OREGON SEPTEMBER 23, 1777 JAMES D. HANLEY

1206

.

<u>\_\_</u>

☆ GPO--798-276