
## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

## HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by Linda Lee Miller in Survey Number 042-1993.

# T4S R38 EH-11



### DESCRIPTION OF CORNER EVIDENCE FOUND:

None. Corner set by Survey 042-1993 appears to have been removed.

SEE SURVEY NUMBER 028-2024

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8 x 30" iron pin, 27" in the ground, with a 2 1/2" aluminum cap marked as shown below, with a 1.5 ft. diam. collar of stone, from which:

#### NEW BEARING OBJECTS:

A 14" White Fir bears South 11° West, a distance of 26.90 feet, marked CS 1/16 S9 BT. A 14" Douglas Fir bears North 81° West, a distance of 22.50 feet, marked CS 1/16 S9 BT.

Set steel fencepost 1 ft. West

I hereby certify that the corner was monumented on August 8th, 2024

Witnesses: Kyle Tucker, Adam Gordon

GRI FFI TH R38E T4S S 1/16 S9 С 2024 **OPLS 83571** 

REGISTERED **PROFESSIONAL** LAND SURWEYOR OREGON June 2, 2010 JEFFREY S. HSU 83571

Renewal Date: June 30, 2025

I use a tape and compass in the establishment of the new bearing objects. I use 14° East declination. Bearings are measured to a brass washer labeled "OPLS 83571" in the BT blaze at the base of the tree. Distances are to a 60D nail in the right side of the base of the center of the tree.

UNION COUNTY **SURVEYOR**