


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner established by Linda Lee Miller in Survey Number 042-1993.

T 4 S R 38 E J-10




DESCRIPTION OF CORNER EVIDENCE FOUND:

None. Corner set by Survey Number 042-1993 appears to have been removed.

SEE SURVEY NUMBER 028-2024

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8 x 30" iron pin, 25" in the ground, with 2 1/2" aluminum cap marked as shown below, from which:



NEW BEARING OBJECTS:

A 7" Douglas Fir bears North 20° East, a distance of 3.00 feet, marked W 1/16 S9 BT.
A 10" Douglas Fir bears South 46° East, a distance of 7.85 feet, marked W 1/16 S16 BT.

Set steel fencepost 1 ft. North.

I hereby certify that the corner was monumented on August 6th, 2024

Witness: Adam Gordon



Renewal Date: June 30, 2025

I use a tape and compass in the establishment of the new bearing objects. I use 14° East declination. Bearings are measured to a brass washer labeled "OPLS 83571" in the BT blaze at the base of the tree. Distances are to a 60D nail in the right side of the base of the center of the tree.

