

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


INDEX FILE NO. L-21

History of original corner establishment:

Original survey by W. Barr, 1881, states:

Marked basalt rock 14x12x4 for 1/4 Sec. Corner.

Raised mound of rock as per instructions.



Description of corner evidence found:

None. Refer to survey filed concurrently with this record.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2"x30" Galvanized Iron Pipe, 27" in the ground with brass cap attached, marked:

From which new BT's:

A 16" Ponderosa Pine, scribed "1/4 S13 BT" on a double blaze, bears S76°E 32.2 ft.

And a 16" Douglas Fir, scribed "1/4 S 13 BT" on a double blaze bears S9°E 31.0 ft.

Attached brass washer marked "LS 1099" to lower blaze of new BT's. Placed fencepost with "ATTENTION" sign attached alongside monument.

Compass declination: 20° East

T4S R38E
 S14 | S13
 1
 4
 PLS 1099
 1981

Witnesses: Gary L. Langlitz PLS 1099
David Allen

Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 29... day of OCTOBER....., 19..81
 .. Howard L. Perry..... by Gary Langlitz.....
 (COUNTY OFFICIAL) (DEPUTY)

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Gary L. Langlitz
 OREGON
 JULY 22, 1977
 GARY L. LANGLITZ
 1099

UNION COUNTY
 SURVEYOR

☆ GPO—798-276
 Date Received 10-29-81

Date Filed 10-29-81

526-84R

File No. 721