


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE No. L-23

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position determined by survey, we set a 5/8"x30" Iron Rod (rod driven at an angle, top bent vertical) with plastic cap marked "APA" attached;

From which a 20" P. Pine, scribed "C 1/4 S13 BT" on a double blaze bears S87°W 119.4 ft.

A 16" P. Pine, scribed "C 1/4 S13 BT" on a double blaze bears S27°E 105.8 ft.


Attached brass washer, marked "LS 1099" to lower blaze of each BT. Placed steel fencepost alongside corner monument.

Corner located approx. 10 ft. West of a jeep road.

Compass Declination: 20° East.

10-1-81

Witnesses: Gary Langlitz
David Allen



Office of.....Surveyor..... County of.....Union.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 29 day of OCTOBER, 1981
 ..Howard L. Perry..... by Gary L. Langlitz.....
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>10-29-81</u>
Date Filed <u>10-29-81</u>
<u>527-84 R</u>
File No. <u>L-23</u>