


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner not previously established.

T 4 S R38 E N-06



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

SEE SURVEY NUMBER 021-2016

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED

TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 22 inches in the ground, in a collar of stone 2 ft. diam, from which:

NEW BEARING OBJECTS:


A 6 inch Ponderosa Pine bears North 58° East, a distance of 104.00 feet, marked W 1/16 S17 BT.

An 8 inch Lodgepole Pine bears South 22° West, a distance of 68.20 feet, marked W 1/16 S20 BT.

I set a steel fencepost approx. 1 foot East of the corner monument. Corner falls 15 feet West of a North/South running fenceline.

I hereby certify that this monument was set July 21, 2016.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2017

BAGETT - GRIFFITH & BLACKMAN

T4S R38E

W 1/16
S17
S20

2016

OPLS 83571

**UNION COUNTY
SURVEYOR**

Date Received 7/21/16

Date Filed 7/21/16

Filed By M. L. G. M.

File Number 027-2016R

I use a steel tape and magnetic compass in the measurement from the bearing trees. Magnetic declination used was 15° East. Bearings are to a brass washer marked OPLS 83571 in the lower blaze.