


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE No. N-23

History of original corner establishment:

Original survey by W. Barr, 1881, states:
Marked basalt rock 15x14x6 for 1/4 sec. corner. Raised mound of rock as per instructions.



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

Corner location determined by survey. Refer to survey map filed concurrently with this record.


At the corner point, set 2"x30" Galvanized Iron Pipe 16" in the ground to bedrock and supported in a mound of stone 4 ft. base, 1 1/2 ft. high, with brass cap attached, marked:

T4S	R38E
1/4	S13 S24
PLS 1099 1981	

Placed steel fencepost with "Attention" sign attached alongside stone mound. No accessories available. N-S fence bears West 55 ft.

10-1-81 Compass Declination: 20° East.

Witnesses: Gary Langlitz
David Allen



Office of..... Surveyor..... County of..... Union.....
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 29 day of OCTOBER, 1981.
 Howard L. Perry..... by Gary Langlitz.....
 (COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR
Date Received <u>10-29-81</u>
Date Filed <u>10-29-81</u>
By <u>531-84 R</u>
File No. <u>N-23</u>