
CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHED:

Corner was originally established under GLO contract number No. 388, dated May 7th, 1881, executed by W. B. Barr. Surveyor General field notes state:

Marked black pine 10 in. diam. for 1/4 sec. corner, from which

Black pine 12 in. diam. bears N50°E 11 lks. dist. Black pine 10 in. diam. bears S20°W 9 lks. dist.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None. A North/South fence line bears approx. 60 ft. East, however remnants of very old North/South fence line were found within 5 ft. of center of Section line to the South.

SEE SURVEY NUMBER 028-2025

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO MONUMENT THE ORIGINAL LOCATION OF THIS CORNER:

At proportionate position, I set a 2 1/2" x 30" aluminum pipe, 28" in the ground, with a 3" aluminum cap marked as shown below, from which:

NEW BEARING OBJECTS:

An 8" diam. Lodgepole Pine bears North 37° East, a distance of 7.50 feet, marked 1/4 S19 BT. A 10" diam. Lodgepole Pine bears South 35° East, a distance of 7.05 feet, marked 1/4 S30 BT. An 8" diam. Lodgepole Pine bears South 59° West, a distance of 20.00 feet, marked 1/4 S30 BT.

An 8" diam. Lodgepole Pine bears North 82° West, a distance of 23.45 feet, marked $1/4~{\rm S19~BT}.$

Set steel fencepost 0.5 feet North


I hereby certify that the corner was monumented on July 24, 2025

Witness: Kyle Tucker

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
June 2, 2010
JEFFREY S. HSU
83571

Renewal Date: June 30, 2027



I use a tape and compass in the establishment of the new bearing objects. 14° East was used for declination and measured to a brass washer labeled "OPLS 83571" in the BT blaze at the base of the tree. Distances are to a 60D nail in the right wide of the base of the center of the tree.

UNION COUNTY
SURVEYOR

Date Received 8/20/25

Date Filed By 033-2075 R

R-03