## **UNION COUNTY SURVEYOR**

## **CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

## HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No record of monumentation found in Union County survey records.

S 26

DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey No. 015-2003

## DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a  $5/8" \times 30"$  iron pin with a  $2\frac{1}{2}"$  aluminum cap marked as shown below, 29" in the ground, from which:

New Bearing Trees:

A 12" diameter Ponderosa Pine bears S 37°W, a distance of 25.53 feet, marked CW 1/16 S26 BT.

A 7" diameter Tamarack bears N  $65^{\circ}W$ , a distance of 25.19 feet, marked CW 1/16 S26 BT.

Set steel fence post approximately 3 feet West of monument.

I hereby certify that the corner was monumented on May 20, 2003.


Witness: Greg Blackman, Jr.

UNION COUNTY
SURVEYOR

Date Received 5/22/03

Date Filed By Lyn, 1. Un

File Number 018-7003 R



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON July 17, 1986

RICK G. ROBINSON

2219

Renewal Date December 31, 2004

I used a magnetic compass and steel tape in the establishment of these accessories. I used a magnetic declination of 18° East, and the distances are to a 50d spike driven on the right side of the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.

T-18