

UNION COUNTY SURVEYOR


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

T 4 S R 38 E U-18

No record of monumentation found in Union County survey records.



DESCRIPTION OF CORNER EVIDENCE FOUND:

None.

See Survey No. 015-2003

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by said survey, I set a 5/8" x 30" iron pin with a 2 1/2" aluminum cap marked as shown below, 26" in the ground, from which:

New Bearing Trees:

An 8" diameter Ponderosa Pine bears S 25°E, a distance of 19.38 feet, marked SW 1/16 S26 BT.

A 12" diameter Douglas Fir bears S 89°W, a distance of 13.95 feet, marked SW 1/16 S26 BT.


Set steel fence post approximately 3 feet North of monument.

Raised small mound of stone around monument.

I hereby certify that the corner was monumented on May 20, 2003.

Witness: Greg Blackman, Jr.

UNION COUNTY SURVEYOR	
Date Received	5/22/03
Date Filed	6/14/03
Filed By	<i>Greg Blackman</i>
File Number	021-2003R



REGISTERED PROFESSIONAL LAND SURVEYOR
<i>Rick G. Robinson</i>
OREGON July 17, 1986
RICK G. ROBINSON 2219

I used a magnetic compass and steel tape in the establishment of these accessories. I used a magnetic declination of 18° East, and the distances are to a 50d spike driven on the right side of the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.

Renewal Date December 31, 2004