History of original comer establishment:

Corner not established in original survey.

| W-1     |        |  |  |
|---------|--------|--|--|
| DIAGRAM |        |  |  |
| T4S     |        |  |  |
| R37E    | R38E   |  |  |
|         | ·      |  |  |
|         | N 1/16 |  |  |
| •       | S 31   |  |  |

No record of subsequent remonumentation found in County records. Description of corner evidence found:

None

See map of survey dated June 1980
Description of monument and accessories I established to perpetuate the original location of this corner:


At proportionate distance I set  $2^{1}2^{1}\times 30^{11}$  iron pipe with brass cap marked as shown,  $23^{11}$  in ground, from which:

A 10 in. dia. fir bears N38E, 14.4 feet marked N 1/16 S31 BT

A 6 in. dia. fir bears \$16W, 24.7 feet marked X BT

A 12 in. dia. fir bears N50W, 25.5 feet marked N 1/16 S36 BT

Raised mound of stone



Date Filed

| REWATERED<br>NAVIGE ENTRY<br>YEVIUS CHAL | 7 |
|--|---|
| And Life                                 |   |
| DUANT L GRIFFIT                          | ¥ |

Brass washer nailed to B.T.blaze Used stgel tape and magnetic compass with 18 East declination. Measured to center of all B.T.s

| Office of              | Measured to center                      | of all B.T.s |
|------------------------|---|--------------|
| State of               | at the within instrument was filed in t | this office  |
| 19 19                  |   | UPHON COUNTY |
| (COUNTY OFFICIAL)      | (DEPUTY)                                |              |
| Form R6-7100-57 (9/71) |   | to Received  |