## **UNION COUNTY SURVEYOR**

## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not originally established under GLO Contract

No record of monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE



See Union County Survey Number 013-2005

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by survey, I set a 5/8"x30" iron pin 27 inches in the ground, with 2 ½" aluminum cap marked as shown, from which:

New Bearing Trees:


An 8 inch diameter Lodge Pole Pine bears N  $67^{\circ}\text{E}$ , a distance of 5.30 feet, marked NW 1/16~BT


A 7 inch diameter Lodge Pole Pine bears N 68°W, a distance of 6.00 feet, marked X BT

Set steel fence post approximately 1 ft. North of monument.

I hereby certify that the corner was monumented on June 23, 2005.

Witness: Gregory T. Blackman, Jr., Mark Brooks





I used a steel tape and magnetic compass in the establishment of these accessories. I used a magnetic declination of 18° East. The distances are to a 50d spike driven on the right side of the root crown. I attached a brass washer marked OPLS 991 to the BT blaze.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON

GREGORY T. BLACKMAN 991

Renewal Date: December 31, 2005

W-06