


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:  
Corner not previously established.

T 4 S R 38 E W - 21



DESCRIPTION OF CORNER EVIDENCE FOUND:  
None

See Survey No. 036-2013

DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED  
TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At position determined by survey, I set a 5/8" x 30" iron pin with 2 1/2" aluminum cap, marked as shown below, 28" in the ground, from which,

A 5/8" x 15" iron pin bears South 40°12' East, a distance of 20.17 feet, with 1 1/2" aluminum cap marked SERP.

A 5/8" x 15" iron pin bears South 48°22' West, a distance of 20.97 feet, with 1 1/2" aluminum cap marked SWRP.


I set a steel fencepost approximately 6 inches West of the corner monument.  
I hereby certify that the corner was monumented on August 13, 2013.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
June 2, 2010  
JEFFREY S. HSU  
83571

Renewal Date: June 30, 2015



**UNION COUNTY  
SURVEYOR**

Date Received 8/14/13

Date Filed 8/14/13

Filed By MLG

File Number 427-2013R

I used a Leica 1200 RTK GPS in the establishment of the accessories. Bearings and distances are to the center of the aluminum cap. Basis of bearing is as per Survey Number 036-2013