

**UNION COUNTY SURVEYOR**


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**HISTORY OF ORIGINAL CORNER ESTABLISHMENT:**

Corner not originally established under GLO Contract

T 4 S R 38 E X - 08

No record of monumentation found in Union County survey records.



**DESCRIPTION OF CORNER EVIDENCE FOUND:**

NONE

See Union County Survey Number 020-2003

**DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED**

**TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:**

At the position determined by survey, I set a 5/8"x30" iron pin 26 inches in the ground, with 2 1/2" aluminum cap marked as shown, from which:

**New Bearing Trees:**

An 8 inch diameter Tamarack bears S 42°E, a distance of 21.66 feet, marked CE 1/16 S32 BT


A 9 inch diameter Douglas Fir bears N 40°W, a distance of 1.20 feet, marked CE 1/16 S32 BT

Set steel fence post approximately 2 ft. South of monument.

I hereby certify that the corner was monumented on July 10, 2003.

Witness: Gregory T. Blackman, Jr.

<b>UNION COUNTY SURVEYOR</b>	
Date Received	8/17/03
Date Filed	9/12/03
Filed By	<i>Gregory T. Blackman, Jr.</i>
File Number	036-200312



<b>REGISTERED PROFESSIONAL LAND SURVEYOR</b>
<i>Rick G. Robinson</i>
<b>OREGON</b> July 17, 1986
<b>RICK G. ROBINSON</b> 2219

Renewal Date December 31, 2004

I used a steel tape and magnetic compass in the establishment of these accessories. I used a magnetic declination of 18° East. The distances are to a 50d spike driven on the right side of the root crown. I attached a brass washer marked OPLS 2219 to the BT blaze.

X-08