## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:
Corner not previously established


DESCRIPTION OF CORNER EVIDENCE FOUND:

NONE

See Survey No. 024-2004

Description of monument and accessories I established to perpetuate the original location of this corner:

At proportionate position determined by survey, I set a  $2\frac{1}{2}$ "x 30" aluminum cap marked as shown from which:



NEW BEARING OBJECTS:

A 5/8" x 30" steel pin with 1 ½ inch aluminum cap bears N 5 31'E, 43.25ft marked NE RP.

A 5/8" x 30" steel pin with 1 ½ inch aluminum cap bears S 5° 09'E, 25.91ft marked SE RP.

A 5/8" x 30" steel pin with 1 ½ inch aluminum cap bears S 51 49'W, 44.41ft marked SW RP.

A  $5/8" \times 30"$  steel pin with 1 ½ inch aluminum cap bears N 36 32'W, 56.19ft marked NW RP.


I hereby certify that the corner was monumented on August 5, 1999 Witness: Mike Spicer ▶

REGISTERED
PROFESSIONAL
LAND SURVEYOR

FREGON
OULY 13, 1973

GREGORY T. BLACKMAN
991

Renewal Date: December 31, 2005



UNION COUNTY
SURVEYOR

Date Received 12/30/04

Date Filed 12/30/04

Filed By P. ROSINSON SKATY

File Number 097-2004 R

The bearing and distance to the iron pins were determined by a GPS observation using a Leica 500 base and receiver. The basis of bearing is that of survey number 024-2004.

C-15