UNION COUNTY SURVEYOR

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Old Book 1 Page 84 states set stone 4"x10"x24" for 1/8 corner Survey No. 040-2002 establishes proportionate position

No record of subsequent monumentation found in the Union County monumentation records Description of corner evidence FOUND:

Found "1/8" chiseled in 3"x10"x26" stone set firmly in mound of stone

See Survey Number 044-2002 Description of monument and accessories I established to perpetuate the original location of this corner:

At the position of found stone, I set a 5/8"x30" iron pin with 2 ½" aluminum cap, marked as shown, 29 inches in the ground, from which NEW BEARING OBJECTS:

A 5/8"x30" iron pin with 1 $\frac{1}{2}$ " aluminum cap, bears North 44° East, a distance of 22.67 feet, in fenceline marked BGB SURVEY MARKER NE RP. A 5/8"x30" iron pin with 1 $\frac{1}{2}$ " aluminum cap, bears North 24° West, a distance of 18.00 feet, in fenceline marked BGB SURVEY MARKER NW RP.

Buried found stone alongside monument. Monument is 17 ft. South of East-West fenceline. Set steel fencepost 1 ft. North of monument

I hereby certify that the corner was monumented on November 22, 2002 Witness: Norbert W. Volny

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 13, 1973

GREGORY T. BLACKMAN
991

Renewal Date: December 31, 2003

S 5
E 1/16
S 8
2002
OPLS 991

T4S R39E E-8

S 5

UNION COUNTY
SURVEYOR

Date Received 12/2/02

Date Filed By P. ROBINSON, DEPUTY

File Number 050-2002 R

I used a Leica 530 GPS system in the establishment of the new accessories. The basis of bearing is the same as shown on Survey No. 044-2002, the distances are to center of the cap.