

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


HISTORY OF ORIGINAL CORNER ESTABLISHMENT:

Corner not previously established.

No monumentation found in Union County survey records.

DESCRIPTION OF CORNER EVIDENCE FOUND:

See Union County Survey Number 003-1998.



DESCRIPTION OF MONUMENT AND ACCESSORIES I ESTABLISHED TO PERPETUATE THE ORIGINAL LOCATION OF THIS CORNER:

At the position determined by the above mentioned survey, 2½" x 30" aluminum pipe with 2½" aluminum cap, marked as shown, 25" in ground, from which:

NEW BEARING OBJECTS:


- A 2" cross chiseled in the most Northwesterly corner of a concrete headwall for an irrigation ditch bears N15°57'E, a distance of 47.61 feet,
- A PK Nail in a Railroad tie fence corner (Nail set 1 ft. Above the ground) bears S78°06'E, a distance of 7.16 feet,
- A 5/8" x 30" rebar bears S57°49'W, a distance of 31.33 feet, with a 1½" aluminum cap marked RP SW
- A 2" cross chiseled in the most Southeasterly corner of a concrete headwall for an irrigation ditch bears N19°26'W, a distance of 37.49 feet, (headwall stamped "1965")

I hereby certify that the corner was monumented on January 15, 1998
Witness: Gregory T. Blackman Jr.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gregory T. Blackman Jr.
OREGON
JULY 13, 1973
GREGORY T. BLACKMAN
991

Renewal Date: December, 31 1999



**UNION COUNTY
SURVEYOR**

Date Received 1-26-98

Date Filed 2-18-98

Filed By R. ROBINSON, DEPUTY

File Number 004-1998R

I used a total station in the establishment of the accessories to this corner. The basis of bearing is the same basis as survey number 003-1998.

G-23