


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX FILE No. ¹~~L-25~~ (~~F45-238E~~)

History of original corner establishment:

Original survey by T. Davenport, 1863, states:

Set quarter Sec. post. Made mound of rock



Description of corner evidence found:


No evidence found.

Refer to survey filed concurrently with this record.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner point as determined by survey, we set a 2"x30" Galvanized Iron Pipe, 22" in the ground and supported in a small mound of rock, with brass cap attached, marked:

Placed steel post with "ATTENTION" sign attached alongside corner monument. Corner located on grassy West slope in old N-S fenceline, no accessories available.



PLS 1099
1981

Witnesses: Gary Langlitz PLS 1099
David Allen

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary L. Langlitz
OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of.....Surveyor..... County of.....Union.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the 29 day of OCTOBER, 1981
.....Howard L. Perry..... by Gary Langlitz.....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY
SURVEYOR

Date Received 10-29-81

Date Filed 10-29-81

548-84R

File No. L-25 (~~F45-238E~~)